



OKLAHOMA DEPARTMENT OF TRANSPORTATION  
SURVEY DIVISION

**FLOOD INFORMATION FORM**

<b>Division #:</b>	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/>
<b>County:</b>	Harmon
<b>Date Highwater occurred:</b>	8/25/2017
<b>Highway Number:</b>	SH-30
<b>Name of Stream:</b>	East Fork Sandy Creek
<b>Direction and distance from nearest town, or highway junction</b>	Approx. 3.40 Miles North of Jct. SH 30 & US62
<b>Section, Township, Range:</b>	Section 14 T 3 N , R 26 W
<b>Description of Location:</b>	Cultivation and grass bar ditch. Water crossed over SH 30 approx. 1000' S. of Sandy Creek Bridge, NBI: 18722
<b>Latitude</b>	34^43'51.34" N
<b>Longitude</b>	99^54'43.39" W
<b>Highwater Elevation:</b>	1651.7 Ft. or Approx. 5" above asphalt approx. 1000' South
<b>Level Datum &amp; Source:</b>	NAVD88 (Computer using GEOID12B)
<b>Method used:</b>	OPUS-RS Solution Utilizing RTK
<b>Date Elevation Obtained:</b>	8/29/2017
<b>Apparent Magnitude:</b>	Normal <input type="checkbox"/> Medium <input checked="" type="checkbox"/> Extreme <input type="checkbox"/> Unknown <input type="checkbox"/>
<b>Was Highwater Mark obtained from actual water, drift, local resident, or other source?</b>	Highwater was obtained from actual drift line.
<b>Explanatory Remarks:</b>	4" to 5" of rain occurred in the area of this location.

Name (Signature) Steve Perring

Name (Printed) Steve Perring

Date 9/7/2017

Note: Show Vicinity Map on back of form

D R

Day

30

36

31

T.L.

T.L.

McKINGHT

6

East

ARNETT

Fork

Highwater  
Elev. 1651



Sandy

T.L.

30

Creek

RAY  
PRESTON  
AIRPORT

HOLLIS  
MUNICIPAL  
AIRPORT

HOLLIS  
POP. 2,264

60' STRIP

4.2

7

0.8

0.5

36

31

Lebos

62

East

7.4

Sandy

Creek

MICHAEL  
AIRPORT

6

Fork

Spring