




**OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION**

FLOOD INFORMATION FORM

| | |
|---|--|
| Division #: | 1 <input type="checkbox"/> 2 <input checked="" type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/> |
| County: | Murray |
| Date Highwater occurred: | 09/25/18 |
| Highway Number: | US 77 |
| Name of Stream: | none |
| Direction and distance from nearest town, or highway junction | .75 miles south of west main in Davis, down along highway 77. |
| Section, Township, Range: | Sec 7 T-1-S R-1-E |
| Description of Location: | Shots taken on centerline of highway in front of Deen's Mini Storage. |
| Highwater Elevation: | 820.9890 |
| Level Datum & Source: | NAVD83 |
| Method used: | GPS Static |
| Date Elevation Obtained: | 05/22/2017 |
| Apparent Magnitude: | Normal <input type="checkbox"/> Medium <input checked="" type="checkbox"/> Extreme <input type="checkbox"/> Don't Know <input type="checkbox"/> |
| Was Highwater Mark obtained from actual water, drift, local resident, or other source? | Got informed from kevin, at the Davis Maintenance barn. |
| Explanatory Remarks: | Flash Flood in that area. Storm curb drain issue. |

Note: Show Vicinity Map on back of form

Name (signature) 
 Name (Printed) Robert Uhles
 Date: 09/26/2018