




OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION

FLOOD INFORMATION FORM

Division #:	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8 <input type="checkbox"/>
County:	Cotton
Date Highwater occurred:	05/2015
Highway Number:	S.H. 53
Name of Stream:	Beaver Creek
Direction and distance from nearest town, or highway junction	Approximately 3.75 miles east of junction of S.H. 65 and S.H. 53 NBI# 29494
Section, Township, Range:	Between Sec. 20 & 29, T-2-S, R-9-W, I.M.
Description of Location:	3.75 miles east of junction S.H. 65 and S.H. 53
Highwater Elevation:	969.5 ft, water was approx. 4 ft. below roadway
Level Datum & Source:	GPS Static observation processed through OPUS.
Method used:	RTK GPS
Date Elevation Obtained:	10/28/2015
Apparent Magnitude:	Normal <input checked="" type="checkbox"/> Medium <input type="checkbox"/> Extreme <input type="checkbox"/> Don't Know <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Highwater mark was obtained after consultation with Cotton County Superintendent Scott Lebarre who stated water was not over the roadway in this area.
Explanatory Remarks:	Shot highwater mark from remnants left on bridge piers. Water never crossed bridge or roadway in this area. There was washout of structure piers underneath bridge but rip rap was now in place.

Note: Show Vicinity Map on back of form

Name (signature) 

Name (Printed)

Derrick E. Anderson

Date: 10/29/2015

Survey Division

Form No. 16

Revised: 5/09/2007

