RVEY DIVISION		**	
HS I	!		Survey Division
WY S-23-S9 RECEIVED	* va * _,vag		Form No. 16
MD there is a factor of the state of the sta	STATE OF OKLA		Rev. 1561 4.00 1981
CC JUL 31 1969 DA			Kraciaral
70	SURVEY DIVIS	ION	AND AND
SURVEY DIVISIONED	ባለው ፓህድለውልለጥፕ	ON TOODM	14AY 28 1969
DO SOURCE CHANGENINE TO	JOD INFORMALI	ON PORM	
p To be used in obtaining and transm	nitting flood	water elevations f	PROBLYKE KANTON
f office record files. This informa			
others in their vicinity in times			
from a reliable source. The elevantering from bridge floor, in relation			
clear manner that fits the situati	ion, the high	est order possible	to be used.
Separate report to be made on each			
OM NIGHT			and the second of the second o
County OKLAHOMA	Date highw	ater occurred MAY	5,1969
Highway number SH 152	Name of st	ream CAMPBELL CR	FEK
		- Office Office	
Direction and distance from neares	t town, vill	age or store 3/4	MILE EAST &
1/2 MILE NORTH WESTERN HEI	COUTE COUGA		
TIZ MILE NORTH WESTERN HET	GHIS SCHOO	<u>L </u>	
The second secon	e e e e e e e e e e e e e e e e		
		; 1 .	
Section, Township and Range SEC.]	<u>7 1 11 N</u>	: R 4 W	
Description of Location INTERSEC	: TION PROPO	SED SH 150 S CAM	DDELL CDEEK
The state of the s	ATTOM TROPO	SED SIL TIE & CAN	FOLL VEEL
Elevation 1240 co	G	11	
Elevation 1249-9	Source or	levels SWO 2478	(1)
Method obtained WYE LEVEL & PHILAD	ELPHIA ROD	Date obtained MAY	5.1969
¥			
Did it appear to be normal	□medium	⊠ extreme □	do not know
Was highwater mark obtained from a	atusl mater	drift local recid	on f
U. S. Engineers, etc.? SILT M	IARKS AND DI	RIFTS THIS INFO	RMATION PLACED ON
PAGE 40 ALIGM. BOOK #1 SWO			
Explanatory Remarks THIS INFORMA	TION ORTAIN	IFD BY V D HINCL	JEE C C D MANAHAN
MAPIGINATOR REMAINS	· · ·	LD DI K.K. HINCE	TEE G S.D. MANAHAN
ON MAY 5,1969. HIGHWATER WA	S CAUSED BY	CA REPORTED 7 M	RAIN WHICH OCCURED
OVER A PERIOD OF APPR	OVEMATELY	O TAO HAHAS	
OVER A PERIOD OF AFFR	ONIMATELL	z z/z nooks.	
Indomedon Daced	mi SWA	271 (11 N	late bust be
Location to be shown on back of th	is sheet as a	check. Liftel	2 5-224
	•	1 1 1	1/2
Field Note: To be sent to		MMI Zin	ellen la
Survey Engineer		X KIN HANK	SKXPSXXXX
	i	ARTING LOCA	TON ENGINEER
	. 1.	MAY 6,1969	
	•	Da	ate

NAC Bridge Owner

LOCATION NO.1

1.00 2.00 2.00 2.00 2.00 2.00 3.00 3.00 4.00 4.00 4.00 4.00 4.00 4		RS	· W				₩	R 4	W .					
		ं व् व	1.4									7		i.
		. • imit e:	;		;							a de la companya de l		i i
											-	di d	i i i i i i i i i i i i i i i i i i i	eptro
		,												1
													•	
	***	33	34	35	36	31	35	33	34	35		40		
		4.	3.	2		7	5		· North	Cana	dian l	, I de en		
5.00	2911	9	10	11/	12	7	- 8	9	10	11			, , , , , , , , , , , , , , , , , , ,	11
sw 4		160	1.5	74	/3	/8	17	Loca	tion h	ighwa	ter	2 H	15 Z	. `
5 W 5	a 11.	21	22	23	24	19	120	lledme 13	Cree ZZ	k 23				;;
3.43	M.	5190g 28	Creek 27	26	25	30	29	28	27	24				
*.	4	. 34									ş			
	<u>.</u>	and the second			AN CO.	C	,	1.		<u>.</u>				· .
, .					CANADI	<u>4</u>					i i	es 2	17.7	1.3
		7 ·			3	ŏ	11	 	ő					
	· ,			Road	35.	्टू	्रे इ	- 00 C	, , , , , , , , , , , , , , , , , , ,			e de la companya de l		
				(N.	4		3				
					Š	2	(X)	, ~×	8	, a	i.			

R5W

R4W