



OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION

FLOOD INFORMATION FORM

Division #:	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8 <input type="checkbox"/>
County:	CADDO
Date Highwater occurred:	04/02/07
Highway Number:	S.H. 58
Name of Stream:	
Direction and distance from nearest town, or highway junction	Location is 4 miles south of the intersection I-40 & S.H. 58, 1 st cross-drain south of intersection S.H. 58 & CR1060.
Section, Township, Range:	SW corner Section 27, T-12-N, R-13-W, I.M.
Description of Location:	Cross-Drain at intersection.
Highwater Elevation:	1637.92
Level Datum & Source:	SAP-775(2) 1951 PLANS
Method used:	Differential Leveling
Date Elevation Obtained:	04/05/07
Apparent Magnitude:	Normal <input type="checkbox"/> Medium <input type="checkbox"/> Extreme <input checked="" type="checkbox"/> Don't Know <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Highwater was taken from a drift and information given by Butch Hannagan, Maintenance Superintendent, Caddo County.
Explanatory Remarks:	

Note: Show Vicinity Map on back of form

Name (signature)

Name (Printed)

Danny R. Dees, PLS

Date:05/30/07

Survey Division

Form No. 16

Revised: 5/09/2007

Loc. No. 20

