

OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION


FLOOD INFORMATION FORM

Division #:	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 X 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/>
County:	Kay
Date Highwater occurred:	04/28/2024
Highway Number:	US-177
Name of Stream:	Stink Creek
Direction and distance from nearest town, or highway junction	Approx. 2.5 miles north of US 60 and US 177 interchange east of Tonkawa
Section, Township, Range:	Sec. 14, T-26-N, R-1-W
Description of Location:	Stink Creek Bridge 2.5 Miles north on US-177 North of US 60 Interchange.
Highwater Elevation:	969.47
Level Datum & Source:	SWO5723(1) NAVD88(2011)
Method used:	RTK
Date Elevation Obtained:	04/29/2024
Apparent Magnitude:	Normal <input type="checkbox"/> Medium <input type="checkbox"/> Extreme <input type="checkbox"/> Don't Know <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Drift line
Explanatory Remarks:	5-7 inches of flash flood rain. Receded quickly after.

Note: Show Vicinity Map on back of form

Name (signature) Robert Jackson II
Name (Printed) Robert Jackson II
Date: 5/01/2024

Stink Creek Bridge Highwater
04/28/2024 Highwater



17

S Main St

17

Hartford Ave

Hartford Ave

W Hartford Ave

W Hartford Ave

