



OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION

FLOOD INFORMATION FORM

Division #:	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input checked="" type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/>
County:	Kiowa
Date Highwater occurred:	5/23/2015
Highway Number:	S.H. 54
Name of Stream:	
Direction and distance from nearest town, or highway junction	23.9 Miles North US62 NBI#13033 30'-40'-30' I-BEAM SPANS
Section, Township, Range:	Between Section 22&23 T-6-N, R-16-W
Description of Location:	North pier column Bridge Pedestal "D" Elev. 1390.0
Highwater Elevation:	1390.5 or 0.5' above bridge pedestal on the North pier column
Level Datum & Source:	STPY 138C 108 S.S. plans
Method used:	Conventional level
Date Elevation Obtained:	5/27/2015
Apparent Magnitude:	Normal <input type="checkbox"/> Medium <input type="checkbox"/> Extreme <input checked="" type="checkbox"/> Don't Know <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Construction worker on the job site gave information from plans used for the construction of the new bridge.
Explanatory Remarks:	New bridge was still under construction.

Note: Show Vicinity Map on back of form

Name (signature) _____
Name (Printed) Daryl Williams
Date:

