


**OKLAHOMA DEPARTMENT OF TRANSPORTATION  
SURVEY DIVISION**

**FLOOD INFORMATION FORM**

|   |  |
|---|--|
| <b>Division #:</b>  | 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 X 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/> |
| <b>County:</b>  | Pottawatomie   |
| <b>Date Highwater occurred:</b>   | 6/26/2007  |
| <b>Highway Number:</b>  | SH177  |
| <b>Name of Stream:</b>  |  |
| <b>Direction and distance from nearest town, or highway junction</b>                          | From the Jct. of SH177 & Hardesty Road go north 0.1 mile to where water was over the south bound lane of SH177.  |
| <b>Section, Township, Range:</b>  | Section 25, T-10-N, R-3-E, I.M.  |
| <b>Description of Location:</b>   | Water over SH177 south bound lane.   |
| <b>Highwater Elevation:</b>   | 999.0  |
| <b>Level Datum &amp; Source:</b>  | NGVD 29 Datum – SWO1991(4)   |
| <b>Method used:</b>   | Differential Leveling  |
| <b>Date Elevation Obtained:</b>   | 7/18/2007  |
| <b>Apparent Magnitude:</b>  | Normal <input type="checkbox"/> Medium <input type="checkbox"/> Extreme X Don't Know <input type="checkbox"/>  |
| <b>Was Highwater Mark obtained from actual water, drift, local resident, or other source?</b> | Highwater mark obtained from Tecumseh Maintenance Crew who witnessed actual water.   |
| <b>Explanatory Remarks:</b>   |  |

Note: Show Vicinity Map on back of form

Name (signature)   
 Name (Printed) Derrick E. Anderson  
 Date: July 18, 2007

