

SURVEY DIVISION
 RLS 5-2-73
 ✓ OCC 5/21/73
 ✓ WFM
 ✓ WVP
 ✓ DOC
 X ✓ 5-8-73
 ✓ 5-8-73

STATE OF OKLAHOMA
 DEPARTMENT OF HIGHWAYS
 SURVEY DIVISION

RECEIVED
 MAY 2 1973
 SURVEY DIVISION

Survey Division
 Form No. 16
 Rev. Sept. 10, 1961

FLOOD INFORMATION FORM

To be used in obtaining and transmitting flood water elevations for Survey Division record files. This information to be obtained by all Chiefs of Party or others in their vicinity in times of unusual high water, or at any time available from a reliable source. The elevations can be recorded by level reading, by measurement from bridge floor, in relation to a house, above roadbed or any other dependable, clear manner that fits the situation, the highest order possible to be used. Separate report to be made on each crossing or place obtained.

County Washington Date highwater occurred April 16, 1973

Highway number US 75 Name of stream Cotton Creek

Direction and distance from nearest town, village or store Approximately 2 1/2 miles north of Copan.

Section, Township and Range Between Sec's. 3 & 4, T-28-N, R-13-E.

Description of Location On present US 75 - 245 Ft. Rt. Sta. 1310+00 on SWO 2730 (1) - US 75 - Washington County. At Culvert approximately 800 Ft. North of present US 75 Cotton Creek Bridge.

Elevation 716.0 Source of levels Mean Sea Level "USC & GS".

Method obtained Wye Level Date obtained April 18, 1973

Did it appear to be normal medium extreme do not know

Was highwater mark obtained from actual water, drift, local resident, U. S. Engineers, etc.? Silt marks after water had receded.
 Obtained by Moran and Basham.

Explanatory Remarks Water overflowed present paving north of present US 75 Cotton Creek Bridge, which halted traffic for several hours.
BM = W. Hdwl 8 X 4 RCB under Present US 75, 244 Ft. Rt. Sta. 1310+00 on SWO 2730 (1).
Elev. of Hdwl as set under SWO 2730 (1) is 615.74 USC&GS Ft.
71534

Location to be shown on back of this sheet as a check.

Field Note: To be sent to
 Survey Engineer

Russ Day 27 Moran Jr
 Location Engineer

April 27, 1973
 Date

5-8-73 THIS INFORMATION WAS SHOWN
 IN THE SWO 2730(1) SURVEY NOTES
 THIS DATE J.P.A.
 MC: BRIDGE DIV.

LOCATION NO. 2

Present US 75 Cotton Creek Bridge
High Water Location

