



OKLAHOMA DEPARTMENT OF TRANSPORTATION
SURVEY DIVISION

FLOOD INFORMATION FORM

Division #:	1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input checked="" type="checkbox"/> 8 <input type="checkbox"/>
County:	Comanche
Date Highwater occurred:	6/27/2021
Highway Number:	S.H. 7
Name of Stream:	N/A
Direction and distance from nearest town, or highway junction	.69 Miles West of S.H. 7 & SE Flower Mound Rd. Junction
Section, Township, Range:	Section 33 T 2 N , R 11 W
Description of Location:	Grass Median & Grass Lined Ditches
Latitude	34^35'40" N
Longitude	98^21'50" W
Highwater Elevation:	1074' Approximately 1" over roadway.
Level Datum & Source:	NAVD88 (Computed using GEOID12B)
Method used:	RTN Solution
Date Elevation Obtained:	7/1/2021
Apparent Magnitude:	Normal <input type="checkbox"/> Medium <input checked="" type="checkbox"/> Extreme <input type="checkbox"/> Unknown <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Highwater was obtained from actual drift line.
Explanatory Remarks:	Approx. 4" to 6" of rain occurred overnight in the upstream area of this location.

Name (Signature) _____

Name (Printed) _____ Lawton Survey

Date _____ 7/7/2021

