

STATE OF OKLAHOMA  
DEPARTMENT OF HIGHWAYS  
SURVEY DIVISION

FLOOD INFORMATION FORM

Survey Division  
Form No. 16  
Rev. Dec. 2, 1974  
JUL 26 1977  
SURVEY DIVISION

To be used in obtaining and transmitting flood water elevations for Survey Division office record files. This information to be obtained by all Chiefs of Party or others in their vicinity in times of unusual high water, or at any time available from a reliable source. The elevations can be recorded by level reading, by measurement from bridge floor, in relation to a house, above roadbed or any other dependable, clear manner that fits the situation, the highest order possible to be used. Separate report to be made on each crossing or place obtained.

County GARVIN Date highwater occurred MAY 20, 1977

Highway number S.H. 19 Name of stream \_\_\_\_\_

Direction and distance from nearest town, village or store APPROX. 5.0 MILES WEST OF INT. S.H. 74 & S.H. 19 IN MAYSVILLE.

Section, Township and Range SECTION 14, T4N, R3W.

Description of Location HIGHWATER OBTAINED AT CENTER OF BRIDGE ON S.H. 19. HIGHWATER 13.5' BELOW LOW STEEL.

Elevation \_\_\_\_\_ Source of levels \_\_\_\_\_

Method obtained TAPE Date obtained MAY 24, 1977

Did it appear to be  normal  medium  extreme  do not know

Was highwater mark obtained from actual water, drift, local resident, U. S. Engineers, etc.? DRIFTS & WATER MARKS ON BANKS.

Explanatory Remarks THE MAYSVILLE AREA RECEIVED 7 INCHES OF RAIN DURING A DELUGE THURSDAY & FRIDAY NIGHTS, MAY 19TH & 20TH CAUSING FLOODING AND THE NEED TO EVACUATE SOME RESIDENTS. TAKEN FROM "THE LINDSAY NEWS" DATED MAY 24, 1977.

Location to be shown on back of this sheet as a check.

Field Note: To be sent to  
Survey Engineer

*Dwight Walden*  
Location Engineer  
July 1, 1977  
Date

*Location No. 20* ⑤

