

STATE OF OKLAHOMA
DEPARTMENT OF HIGHWAYS
SURVEY DIVISION

Survey Division

Form No. 16
Rev. Dec 2, 1974

JUL 26 1977

FLOOD INFORMATION FORM

SURVEY DIVISION

~~Survey Division~~

To be used in obtaining and transmitting flood water elevations for office record files. This information to be obtained by all Chiefs of Party or others in their vicinity in times of unusual high water, or at any time available from a reliable source. The elevations can be recorded by level reading, by measurement from bridge floor, in relation to a house, above roadbed or any other dependable, clear manner that fits the situation, the highest order possible to be used. Separate report to be made on each crossing or place obtained.

County GARVIN Date highwater occurred MAY 20, 1977

Highway number S.H. 19 Name of stream _____

Direction and distance from nearest town, village or store APPROX. 3.0 MILES

WEST OF INT. S.H. 74 & S.H. 19 IN MAYSVILLE.

Section, Township and Range SECTION 13, T4N, R3W.

Description of Location HIGHWATER OBTAINED AT SOUTH TOP OF OPENING OF 2'x2'

R.C.B. ON S.H. 19. HIGHWATER 1.2' ABOVE TOP OF OPENING OF R.C.B.

Elevation _____ Source of levels _____

Method obtained HAND LEVEL Date obtained MAY 24, 1977

Did it appear to be normal medium extreme do not know

Was highwater mark obtained from actual water, drift, local resident, U. S. Engineers, etc.? DRIFTS & WATER MARKS ON SOUTH END OF R.C.B.

Explanatory Remarks THE MAYSVILLE AREA RECEIVED 7 INCHES OF RAIN DURING A DELUGE

THURSDAY & FRIDAY NIGHTS MAY 19TH & 20TH, CAUSING FLOODING AND THE NEED TO EVACUATE

SOME RESIDENTS. THIS INFORMATION TAKEN FROM "THE LINDSAY NEWS" DATED MAY 24, 1977.

Location to be shown on back of this sheet as a check.

Field Note: To be sent to
Survey Engineer

Newaynes Walden
Location Engineer

7-1-77
Date

Location No. 190

