

OKLAHOMA DEPARTMENT OF TRANSPORTATION **SURVEY DIVISION**

FLOOD INFORMATION FORM

1
Kay
04/28/2024
US-177
Drainage ditch along US 177
Approx. 2.2 miles south of SH 11 and US 177 interchange in
Blackwell.
Sec. 35, T-27-N, R-1-W
Approx. 1000' south of Chrysler Ave and US 177. In the vicinity of
Nash Ave intersection of Highway 177.
1016.32
SWO5723(1) NAVD88(2011)
RTK
04/29/2024
Normal Medium Extreme Don't Know X
Drift line
5-7 inches of flash flood rain. Receded quickly after. Drainage ditch
was not keeping up with rainfall amounts

Note: Show Vicinity Map on back of form

Robert Jackson II Name (signature) Robert
Name (Printed) Robert Jackson II

Date: 5/01/2024

Survey Division Form No. 16

Revised: 5/09/2007

