

STATE OF OKLAHOMA
DEPARTMENT OF HIGHWAYS
SURVEY DIVISION

FLOOD INFORMATION FORM


To be used in obtaining and transmitting flood water elevations for Survey Division office record files. This information to be obtained by all Chiefs of Party or others in their vicinity in times of unusual high water, or at any time available from a reliable source. The elevations can be recorded by level reading, by measurement from bridge floor, in relation to a house, above roadbed or any other dependable, clear manner that fits the situation, the highest order possible to be used. Separate report to be made on each crossing or place obtained.

County MURRAY Date highwater occurred MAY 20, 1977.

Highway number US 77 Name of stream WASHITA RIVER

Direction and distance from nearest town, village or store 3.5 MILES SOUTH OF DAVIS;

OKLAHOMA, JUST NORTH OF ICT. US 77 & I-35



Section, Township and Range SEC. 19, T1S, R2E.

Description of Location BRIDGE IS LOCATED 3.5 MILES SOUTH OF DAVIS, OKLA.

ON US 77, IN THE NE $\frac{1}{2}$, SEC. 19, T1S, R2E.

Elevation 788.5 (UPSTREAM) Source of levels USC&GS

Method obtained ENGINEERING LEVEL Date obtained JUNE 1, 1977.

Did it appear to be normal medium extreme do not know

Was highwater mark obtained from actual water, drift, local resident, U. S. Engineers, etc.? VISIBLE WATER MARK. LOCATED APPROX. 200 FEET

WEST OF THE SOUTH END OF BRIDGE AT FENCE CORNER.

Explanatory Remarks THIS HIGHWATER MARK WAS 17.5 FT. LOWER THAN THE

BRIDGE FLOOR AT THE SOUTH END. THE BRIDGE FLOOR AT THE SOUTH END

IS 10.5 FT. HIGHER THAN EXTREME HIGHWATER. THE HIGHWATER ON MAY 20,

1977, WAS FROM 7.0 FT. TO 8.5 FT. LOWER THAN EXTREME HIGHWATER IN 1950.

Location to be shown on back of this sheet as a check.


Field Note: To be sent to
Survey Engineer

Bobby Earl Garland
Chief of Party

JUNE 1, 1977
Date

FILE: FLOOD INFO. MURRAY Co. ✓
M: BRIDGE DIV. 6/2/77

Location No. 2



T
1
S

R 2 E