



OKLAHOMA DEPARTMENT OF TRANSPORTATION  
SURVEY DIVISION

FLOOD INFORMATION FORM

Division #:	1 X 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6 <input type="checkbox"/> 7 <input type="checkbox"/> 8 <input type="checkbox"/>
County:	Okmulgee
Date Highwater occurred:	5/25/2016
Highway Number:	US 75A
Name of Stream:	Railroad Underpass
Direction and distance from nearest town, or highway junction	0.9 Miles North of Jct. SH 16 & US 75A in Beggs.
Section, Township, Range:	Section 30, T-15-N, R-12-E
Description of Location:	
Highwater Elevation:	733.30'
Level Datum & Source:	NAVD 88 -SWO 4457(1)
Method used:	RTK
Date Elevation Obtained:	5/31/2016
Apparent Magnitude:	Normal <input type="checkbox"/> Medium <input type="checkbox"/> Extreme X Don't Know <input type="checkbox"/>
Was Highwater Mark obtained from actual water, drift, local resident, or other source?	Drift and Confirmed with Okmulgee County Maintenance Supervisor.
Explanatory Remarks:	

Note: Show Vicinity Map on back of form

Name (signature) \_\_\_\_\_

Name (Printed) Shannon D. Harris

Date: 5/31/2016

